

TECHNICAL CIRCULAR No. 096 of 31st December 2012

To: All Surveyors/Auditor

Applicable to flag: All Flags

Subject: Periodic servicing of free-fall lifeboat release systems

Reference: SOLAS - Amendment to SOLAS regulation III/20.11.2

Conarina has a statutory alert regarding periodic servicing of free-fall lifeboat release systems in accordance with amendment to SOLAS regulation III/20.11.2

Lifeboats should be tested regularly to ensure they operate when needed and that crews know how to operate them. For testing of free-fall lifeboats a physical launch is not always appropriate, and there is an element of risk to crews.

An amendment to SOLAS chapter III, regulation 20.11.2.4 which will enter into force on 1 January, 2014, will permit operational testing of free-fall lifeboats to be performed either by free-fall launch, with only the operating crew on board, or by a simulated launch in accordance with MSC.1/Circ.1206/Rev.1.

The IMO has issued circular MSC.1/Circ.1411 to encourage all parties concerned to implement the amendment at the earliest opportunity.

In the interests of safety, shipowners and managers with responsibility for ships which have free-fall lifeboats are encouraged to take note of the circular and act accordingly.



Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117, E-Mail:

joel@conarinagroup.com

Technical Head Office

7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 1 of 2

REFERENCES:

Amendment to SOLAS regulation III/20.11.2

ATTACHMENTS: No.

Kindest Regards, Cosmin Bozenovici Naval Architect - Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117, E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363,

1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 2 of 2